


Note: This map was developed by H2R Engineering using readily available information and is not based on a field survey. Information shown is approximate.



Outfall Information Table

Unique ID <sup>1</sup>	Latitude	Longitude	Est. DCC Regulated Drainage Area (acres)
OF-1	36° 33' 46.54" N	79° 24' 29.35" W	0.2
OF-2	36° 33' 49.00" N	79° 24' 30.98" W	0.3
OF-3	36° 33' 51.14" N	79° 24' 29.12" W	16.8
OF-4	36° 33' 50.44" N	79° 24' 30.72" W	0.7
OF-5	36° 33' 50.34" N	79° 24' 33.09" W	1.4
OF-6	36° 33' 53.01" N	79° 24' 35.23" W	0.6
OF-7	36° 33' 54.47" N	79° 24' 35.20" W	0.3
OF-8	36° 33' 50.69" N	79° 24' 29.74" W	2.1
OF-9	36° 33' 56.54" N	79° 24' 36.16" W	1.3
OF-10	36° 33' 51.34" N	79° 24' 36.59" W	0.2
OF-11	36° 33' 47.14" N	79° 24' 32.26" W	0.9
OF-12	36° 33' 51.38" N	79° 24' 40.68" W	1.6
OF-13	36° 33' 50.15" N	79° 24' 39.52" W	0.1
OF-14	36° 33' 48.75" N	79° 24' 38.30" W	0.2
OF-15	36° 33' 48.23" N	79° 24' 37.51" W	0.3
OF-16	36° 33' 39.81" N	79° 24' 33.96" W	1.0
OF-17	36° 33' 49.27" N	79° 24' 41.07" W	0.8
OF-18	36° 33' 50.31" N	79° 24' 35.76" W	0.1

<sup>1</sup> For all outfalls: (1) Predominant land use = Institutional; (2) the receiving waters is the Dan River – Pumpkin Creek (RD39) that is designated as impaired (benthic) in the Virginia 2016 305(b)/303(d) Water Quality Assessment Integrated Report; (3) No total maximum daily load waste load allocations have been assigned.

- Legend
- Pervious
  - Building
  - Road
  - Sidewalk
  - SWM Facility
  - Forest / undeveloped
  - Flow direction
  - Storm sewer
  - Storm channel/swale
  - Storm structure

Abbreviations

BMP = Stormwater Facility Best Management Practice  
OF = MS4 Outfall  
POI = Point of interconnection with the City MS4

For additional information regarding stormwater facility BMPs, see the VHCC BMP Database.

**DCC**  
Danville Community College

**MS4 Mapping**  
Latest Revision: June 2023

0 50 100 200  
SCALE IN FEET